# 10/608398

Cold

Docket No.: PROTOM 3.0-029 II (PATENT)

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of: Jin Chen Chuang

Patent No.: 6,880,840

Issued: April 19, 2005

For: CAMBERING VEHICLE HAVING

FOLDABLE STRUCTURE

Certificate
MAY 2 3 2005

of Correction

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

### REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323

Dear Sir:

Enclosed herewith is an original and one copy of a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the copy of the Certificate of Correction duly certified.

Dated: May 12, 2005

Respectfully submitted,

Scott E. Charney

Registration No.: 51,548 LERNER, DAVID, LITTENBERG,

KRUMHOLZ & MENTLIK, LLP 600 South Avenue West Westfield, New Jersey 07090

(908) 654-5000

Attorney for Applicant

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

### UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page <u>1</u> of <u>1</u>

PATENT NO.

6,880,840

APPLICATION NO. :

10/608.398

ISSUE DATE

April 19, 2005

INVENTOR(S)

Jin Chen Chuang

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 13, "vehicle" should read --vehicles--.

Column 1, line 16, "laterally spaced" should read -- laterally-spaced--.

Column 1, line 20, "and to result" should read -- to result in --.

Column 1, line 38, "One" should read -- On --.

Column 1, line 42, cancel the word "be".

Column 1, line 43, "travels" should be --travel--.

Column 2, line 8, the first occurrence of "detachably" should read --detachable--.

Column 2, line 10, "arm" should read --arms--.

Column 2, line 11, "arm" should read --arms--.

Column 2, line 23, "on bottom" should read -- on the bottom --.

Column 3, line 22, "attached to" should read -- attached to the --.

Column 3, line 31, insert a comma after 35.

Column 4, line 32, insert -- are -- after 40.

Column 4, line 56, insert -- in -- after the word "result".

Column 4, line 61, insert --a-- before the word "different".

Column 5, line 1, "cause different" should read -- cause a different --.

Column 5, line 57, "arm" should read -- arms --.

Column 5, line 59, "arm" should read -- arms --.

Column 6, line 11, "on bottom" should read -- on the bottom --.

Column 6, line 40, "sock et" should read --socket--.

MAILING ADDRESS OF SENDER (Please do not use customer number below): Scott E. Charney LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP 600 South Avenue West

Westfield, New Jersey 07090

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTC-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page \_1\_ of \_1\_

PATENT NO.

6,880,840

APPLICATION NO.

10/608,398

ISSUE DATE

April 19, 2005

INVENTOR(S)

Jin Chen Chuang

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 13, "vehicle" should read --vehicles--.

Column 1, line 16, "laterally spaced" should read -- laterally-spaced--.

Column 1, line 20, "and to result" should read -- to result in --.

Column 1, line 38, "One" should read -- On --.

Column 1, line 42, cancel the word "be".

Column 1, line 43, "travels" should be --travel--.

Column 2, line 8, the first occurrence of "detachably" should read --detachable--.

Column 2, line 10, "arm" should read --arms--.

Column 2, line 11, "arm" should read --arms--.

Column 2, line 23, "on bottom" should read -- on the bottom --.

Column 3, line 22, "attached to" should read -- attached to the --.

Column 3, line 31, insert a comma after 35.

Column 4, line 32, insert -- are -- after 40.

Column 4, line 56, insert -- in -- after the word "result".

Column 4, line 61, insert --a-- before the word "different".

Column 5, line 1, "cause different" should read -- cause a different --.

Column 5, line 57, "arm" should read -- arms --.

Column 5, line 59, "arm" should read -- arms --.

Column 6, line 11, "on bottom" should read -- on the bottom --.

Column 6, line 40, "sock et" should read --socket--.

MAILING ADDRESS OF SENDER (Please do not use customer number below): Scott E. Charney LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP 600 South Avenue West Westfield, New Jersey 07090